

Firmup_SMARTY_090805

This version runs both on Vista 32 and Vista 64.

Firmware Slave Processor 47.05.02

- Improved GPS lap marker

EVO4 43.02.16

- No changes

MXL 14.86.44

- Fixed Bug "Bad Configuration" on MXL Pro05 (only for MXL15/A board)

EVO3 28.08.26

- First official release that supports SmartyCam and Channel Expansion
- Doesn't support David

ECU Bridge 45.01.03

- First official release

Firmup_SMARTY_090724

Firmware Slave Processor 47.05.01

- No changes

EVO4 43.02.16

- Improved CAN management

MXL 14.86.43

- No changes

EVO3 28.08.25

- No changes

Firmup_SMARTY_090703

Firmware Slave Processor 47.05.01

- No changes

EVO4 43.02.15

- No changes

MXL 14.86.43

- No changes

EVO3 28.08.25

- SmartyCam management by EVO3 added

Firmup_MXL_EVO4_SMARTY_090630

Firmware Slave Processor 47.05.01

- Added Management SPI for firmup using microSD

EVO4 43.02.15

- Improved GPS Lap Timing

MXL 14.86.43

- Improved SmartyCam and Channel Expansion management
- Fixed Memkey bug